5,000 g FORCE GAUGE

Model: FG-5000A

ISO-9001, CE



5 Kg full scale, Model: FG-5000A



FEATURES

- 5,000 g maximum capacity, high resolution, accuracy & repeatability.
- * Display unit: gram, Newton & oz.
- * Tension & compression capability.
- * Peak hold (Max. load).
- Zero button.
- Full capacity zero (tare) control.
- * Fast/Slow response time push button.
- * Positive or reverse direction select.
- * Full line accessories (adapters).
- * Hand held & stand mounted available.
- * Microprocessor circuit & exclusive load cell transducer.
- * Over load protection.
- * RS-232 computer interface (optional).
- Professional test stand (optional).



Test stand, optional Model: FS-1001



The Art of Measurement

LUTRON ELECTRONIC

5 Kg FORCE GAUGE, Model: FG-5000A

FEATURES			
* Wide capacity, high resolution, high accuracy,	* Positive or reverse display direction select.		
high repeatability.	* Full line accessories (adapters) are included.		
* 3 kind display unit.	* Hand held & stand mounting available.		
* Tension & compression capability .	* Low power consumption gives long battery life.		
* Peak hold (Max. load) can be held in display	* Build in low battery indicator.		
during make tension or compression measurement.	* Microprocessor circuit & exclusive load cell		
* Zero button can operate both for normal measuring	transducer.		
& the " peak hold " operation.	* Over load protection.		
* Full capacity zero (tare) control capability.	* RS-232 computer interface (optional).		
* Fast/Slow response time push button.	* Professional test stand (optional).		

SPECIFICATIONS					
Display	LCD (Liquid crystal display).	Full Scale	Approx. 2.0 mm max.		
	5 digits, 10 mm (0.4") digit size.	Deflection			
Display	Positive or Reverse direction, select by	Power Supply	6 x 1.5 V AA (UM-3) size battery		
Direction	the push button on the front panel.		or DC 9V adapter (not included).		
Function	Tension & Compression (Push & Pull).	Power	Approx. DC 24 mA		
	Normal force, Peak hold (Max. load)	Consumption			
Peak hold	Will freeze the display value of the	Transducer	Exclusive load cell.		
	Peak load (Max. load).	Operating	$0^{\circ}\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!\!$		
Zero	Zero button can be operated both for	Temperature			
	"normal force" or "peak hold" operation.	Operating	Less than 80% RH.		
Measure	5000 g/176.40 oz/49.03 Newton.	Humidity			
Capacity		Dimension	227 x 83 x 39 mm (8.9 x 3.3 x 1.5 inch).		
Resolution	1 g/0.05 oz/0.01 Newton.	Weight	551 g (1.2 LB)/with batteries.		
Min. Display	3 g/0.10 oz/0.03 Newton.	Mounting	Mounting holes are provided on the		
Accuracy	\pm (0.4 % + 1 d), within 23± 5°C.	Holes	back case, easy stand mounting.		
Unit select	g/oz/Newton	Data output	Optional,		
Update time	Fast Approx. 0.2 second.		RS-232 serial computer interface		
	Slow Approx. 0.6 second.	Accessories	Operating manual1 PC.		
Over range	Display show " " when in over	Included	Flat-head adapter1 PC.		
Indicator	range status.		Hook adapter 1 PC.		
Overload	Max. 7 kg.		Cone head adapter 1 PC.		
Capacity			Chisel head adapter1 PC.		
Zero/tare	Max. full capacity.		120 mm extension rod 1 PC.		
Control			Carrying case 1 PC.		
Circuit	Exclusive microprocessor LSI-circuit.	Optional	Test stand, Model: FS-1001		
		Accessories	Wedge grip, Model: WG-01		

OPTIONAL EQUIPMENT & ACCESSORY

TEST STAND	Test stand, cooperate with Force gauge FG-20KG, FG-5000A, whole system will be
Model : FS-1001	become the useful tool for material's tension & compression analysis.
	Size: 630 x 250 x 230 mm. Weight: 7.02 Kg (15.4 LB).
Wedge grip	Wedge grip, the optional accessory to install to the base of FS-1001 be used to hold
Model: WG-01	the tested material.

FORCE GAUGE with RS-232 COMPUTER INTERFACE

FG-5000A-RS232	All the function are same as the FG-5000A but with RS-232 computer interface.
SW-U101-WIN	Software for data logging & data recorder.

 $^{^{\}star}$ Appearance and specifications listed in this brochure are subject to change without notice.

FORCE GAUGE

Model: FS-1001 *ISO-9001, CE, IEC1010*



FEATURES

- * Optional; test stand, be connected with FG-5000A, FG-20KG, FG-5000A-232, FG-20KG-232, whole system will be a useful tool for material's tension and compression analysis.
- * Size: 650 x 250 x 230 mm.





The Art of Measurement