

## 101211 FIT+ three Starter Kit Propane



### FIT+ three Starter Kit Propan Spare & wear parts

#### *FIT+ three Starter Kit Propan Verschleiss- und Ersatzteile*

consisting of / bestehend aus je

|        |                                               |             |
|--------|-----------------------------------------------|-------------|
| 100797 | TOOL-FREE HEATING NOZZLE GSF PC, 3-150 mm (A) | 1 pcs / Stk |
| 100888 | TOOL-FREE CUTTING NOZZLE FIT+ PSF 7-15 mm     | 1 pcs / Stk |
| 100889 | TOOL-FREE CUTTING NOZZLE FIT+ PSF 15-25 mm    | 1 pcs / Stk |
| 100890 | TOOL-FREE CUTTING NOZZLE FIT+ PSF 25-40 mm    | 1 pcs / Stk |
| 100891 | TOOL-FREE CUTTING NOZZLE FIT+ PSF 40-60 mm    | 1 pcs / Stk |
| 100892 | TOOL-FREE CUTTING NOZZLE FIT+ PSF 60-100 mm   | 1 pcs / Stk |
| 101180 | SPARE O-RINGS FIT+                            | 1 pcs / Stk |
| 101182 | CONICAL CLEANING NEEDLE                       | 1 pcs / Stk |
| 100777 | SPLASH PROTECTOR, IHT 6200-1-504              | 1 pcs / Stk |
| 100779 | TORCH SETTING TOOL, IHT 6200-1-               | 1 pcs / Stk |
| 100774 | O-RING, IHT 6200-1-503                        | 1 pcs / Stk |
| 100773 | CLEARANCE SENSOR, IHT 6200-1510 Type B 14/19- | 1 pcs / Stk |
| 100780 | CONTACT PIN, IHT 6200-1-505                   | 1 pcs / Stk |
| 100778 | PIN TOOL, IHT 6200-1-401                      | 1 pcs / Stk |
| 100781 | CLEARANCE SENSOR EJECTOR, IHT 6200-1-230      | 1 pcs / Stk |
| 101165 | FLASH BACK ARRESTOR CUTTING O2 G3/8"          | 1 pcs / Stk |
| 101166 | FLASH BACK ARRESTOR HEATING O2 G1/4"          | 1 pcs / Stk |
| 101167 | FLASH BACK ARRESTOR FUEL GAS G3/8"LH          | 1 pcs / Stk |
| 101181 | CLEANING BRASS BRUSH                          | 1 pcs / Stk |

## 101213 FIT+ three Starter Kit Acetylene



### **FIT+ three Starter Kit Acetylene Spare & wear parts**

### ***FIT+ three Starter Kit Azetylen Verschleiss- und Ersatzteile***

consisting of / bestehend aus je

|        |                                               |             |
|--------|-----------------------------------------------|-------------|
| 100797 | TOOL-FREE HEATING NOZZLE GSF PC, 3-150 mm (A) | 1 pcs / Stk |
| 100894 | TOOL-FREE CUTTING NOZZLE FIT+ ASF 6-10 mm     | 1 pcs / Stk |
| 100895 | TOOL-FREE CUTTING NOZZLE FIT+ ASF 10-25 mm    | 1 pcs / Stk |
| 100896 | TOOL-FREE CUTTING NOZZLE FIT+ ASF 25-40 mm    | 1 pcs / Stk |
| 100897 | TOOL-FREE CUTTING NOZZLE FIT+ ASF 40-60 mm    | 1 pcs / Stk |
| 100898 | TOOL-FREE CUTTING NOZZLE FIT+ ASF 60-100 mm   | 1 pcs / Stk |
| 101180 | SPARE O-RINGS FIT+                            | 1 pcs / Stk |
| 101182 | CONICAL CLEANING NEEDLE                       | 1 pcs / Stk |
| 100777 | SPLASH PROTECTOR, IHT 6200-1-504              | 1 pcs / Stk |
| 100779 | TORCH SETTING TOOL, IHT 6200-1-               | 1 pcs / Stk |
| 100774 | O-RING, IHT 6200-1-503                        | 1 pcs / Stk |
| 100773 | CLEARANCE SENSOR, IHT 6200-1510 Type B 14/19- | 1 pcs / Stk |
| 100780 | CONTACT PIN, IHT 6200-1-505                   | 1 pcs / Stk |
| 100778 | PIN TOOL, IHT 6200-1-401                      | 1 pcs / Stk |
| 100781 | CLEARANCE SENSOR EJECTOR, IHT 6200-1-230      | 1 pcs / Stk |
| 101165 | FLASH BACK ARRESTOR CUTTING O2 G3/8"          | 1 pcs / Stk |
| 101166 | FLASH BACK ARRESTOR HEATING O2 G1/4"          | 1 pcs / Stk |
| 101167 | FLASH BACK ARRESTOR FUEL GAS G3/8"LH          | 1 pcs / Stk |
| 101181 | CLEANING BRASS BRUSH                          | 1 pcs / Stk |